

# Village of East Dundee, IL Automated Photo Enforcement Program

## 36 Month Statistical Analysis

IL 68 (Penny Ave) & IL 72 (Main St) – Southbound  
Camera Installation – September 11, 2009  
2006 – 2008 (RLRC 3yrs prior)  
2010 – 2012 (RLRC 3yrs post)

	Rear-End	Angle	Turning	Other	Injured	Killed	Total
IDOT crash data 2006	14	0	2	1	1	0	17
IDOT crash data 2007	14	1	3	2	2	0	20
IDOT crash data 2008	12	0	1	1	2	0	14
IDOT crash data 2009	4	0	4	0	2	0	8
IDOT crash data 2010	3	0	3	0	2	0	6
IDOT crash data 2011	4	0	1	1	2	0	6
IDOT crash data 2012	4	1	1	0	1	0	6

- Other indicates the following: Pedestrian, Pedalcyclist, Fixed Object, and Sideswipe

Compared to pre-camera installation annual averages:

- Rear End crashes post-installation have decreased by **72%**
- Turning crashes post-installation have decreased by **15%**
- Other crashes post-installation have decreased by **77%**
- Total crashes have decreased by **65%**

*\*All data is based on information derived from multiple sources and distributed by the Illinois Department of Transportation. The Village of East Dundee is not responsible for the accuracy of the data contained herein.*